

09830818-090401




FIG. 1

TOH060" 8T80EE860

09/830818




FIG. 2




FIG. 3

09830818-090401

09830818 090401

09/830818




FIG. 4




FIG. 5

FIG. 6




FIG. 7

FIG. 7

52 →





FIG. 8



53

FIG. 9




FIG. 1050-87808860




Fig. 104060-8180E860

56




FIG. 12

57 →




FIG. 14




FIG. 15





Fig. 16



510

FIG. 17





Fig. 18




FO4060" BT30E860

09/830818

S10

FIG. 19



SM →

FIG. 20





FIG. 21






Fig. 23




24
21

7

55

51

45






Fig. 27

